



Aftermarket DPF, DOC, Clamps,
Gaskets & Sensor Program

Aftertreatment, Accessories & Sensor Catalog



DPFXFIT™ by GESi®

www.dpfxfit.com | 1.888.758.4374

The DPFxFIT™ Advantage: Why Our Program Works For You

- ✕ Complete line of aftermarket DPF and DOCs designed as an OEM replacement
- ✕ All makes coverage for light, medium & heavy-duty applications
- ✕ Substrates sourced from tier-1 OEM suppliers and coated in-house with platinum group metals
 - Strict internal quality control ensures entire substrates are completely coated with precious metals
- ✕ One-piece canister made from high quality stainless steel
- ✕ All units include OEM clamps and gaskets
- ✕ 3-year unlimited mileage warranty
- ✕ Industry leading packaging to ensure products arrive in the same condition they were shipped
- ✕ Always new, never re-manufactured with no core charges
- ✕ Clamps, gaskets & sensors available
- ✕ Providing quick turnaround times with a responsive customer service team that offers coast to coast coverage and support



Find Your OE Replacement Today



OEM DURABILITY & PERFORMANCE WITH AFTERMARKET AFFORDABILITY!

About Global Emissions Systems Inc. (GESi®)

Global Emissions Systems Inc. (GESi®) specializes in designing, engineering, and manufacturing of world-leading emission control technologies for all types of engines, using any commercially available fuel. With over 25 years of experience, we have invested in the research, development, and testing of advanced emission solutions for on-road, off-road, marine, and stationary applications.

The GESi® advantage stands out for its North American-built aftertreatment solutions, prioritizing quality and performance. Our patented technologies help partners achieve the highest levels of emission reductions. The GESi® technology has been verified by all major independent third-party labs including CARB, EPA, ETV, and EURO. Our products can be integrated at the time of manufacture or retrofitted into any existing engine installation.

Headquartered in Ontario, Canada, GESi® expanded into the United States in 2020 with a coating facility near Charlotte, North Carolina. We emphasize vertical

integration, managing everything from raw material sourcing to final assembly, which results in cost-effective solutions for our customers.

For the high-performance automotive market, we offer G-Sport™ by GESi®, a complete line of universal, high-flow EPA-compliant catalytic converters designed for the harshest, high-horsepower applications. Our DPFxFIT™ brand serves the heavy-duty on-road market, providing diesel particulate filters and diesel oxidation catalysts for light, medium, and heavy-duty trucks. DPFxFIT™ products meet or exceed OEM requirements, with filters catalyzed with platinum group metals for optimal performance—always new, never remanufactured.

Additionally, GESi® is heavily involved in supplying the industrial industry, retrofitting engines for both primary and backup power in emergency situations. With our expertise in project solutions, we can custom engineer after-treatment systems to meet any application and emission requirement.

GESi® Mission

Design, Engineer, Manufacture, Sell, and Support, emissions technologies by exceeding the expectations of our partners and our industry.



Leader in Emissions
Control Solutions

www.gesi.us



Performance Without
Compromise

www.gsportbygesi.com



OEM Durability & Performance
with Aftermarket Affordability

www.dpfxfit.com





Product Image	Part Number	Engine Model	Clamp Numbers	Gasket Numbers	OEM/Aftermarket Part Numbers
	GESi-0001	ISX	CL-0003	G-0003	4388410, 4965129, 4965226, 4969700, 4969701, 4969702, 5283669, 5283778, 5297522, 5297990, 5579290, 5579291, 2596665C91, 2596665R91, 2601229C91, 2601229C92, 2601229C93, 2607031C1, 2880168NX, 3817964C91, 3817989C91, 3817990C91, 4388409RX, 4388410RX, 4965129NX, 4965226NX, 4969700NX, 4969701NX, 4969702NX, 5010848R1, 5010851R1, 5283669NX, 5283778NX, 5297522NX, 5297990NX, 5579290RX, Q621936, Q621944, Q622369 C0001-SA, C0030-SA, C0063-SA, 58001, 65015, 65016, 82002, XN1101, XN1105, 1N1202, 1N1210, GESi-0023, GESi-0033
	GESi-0002	ISM & ISL	CL-0003	G-0003	2880169, 4352920, 4352923, 4936737, 4965055, 4965244, 5633691, 5633688, 2606777C1, 2606911C1, 2817962C91, 2880169NX, 3623370C93, 3817962C91, 4352920NX, 4352920RX, 4352923NX, 4936737NX, 4936737RX, 4965055D, 4965055NX, 4965055RX, 4965244NX, N8894071, Q621378 C0004-SA, C0018-SA, 58004, 65012, MN1001, MN1002, MN0405, GESi-0016, GESi-0058

For more information on how to register/gain access please reach out to: orders@gesi.us

Due to industry changes, modifications and/or consolidations to aftermarket and/or OEM designs, please double-check your cross reference at www.dpfxfit.com to ensure accuracy and that you are using the most current information

Product Image	Part Number	Engine Model	Clamp Numbers	Gasket Numbers	OEM/Aftermarket Part Numbers
	GESi-0009	ISL	CL-0002	G-0002	2871463NX, 2871463, 5579355, 2871463RX, 5579355NX, 5579355RX, Q629362 C0062-SA, 58006, LJ1204
	GESi-0010	ISM	CL-0003	G-0003	4352922, 4965218, 4352922NX, 4965218NX MN1004
	GESi-0017	ISC & PX8	CL-0002	G-0002	4965286, 621371, 623316, 623804, 4965229, 4969838, 4969839, 5579352, 5579353, 4965229NX, 4965286NX, 4965286RX, 4969838NX, 4969838RX, 4969839NX, Q621371, Q622316, Q623316, Q623804 C0003-SA, 58003, CJ1201, CJ1203
	GESi-0018	ISB & PX6	CL-0001	G-0001	4965227, 5578363, 5579363, 5579364, 4965227NX, 4965227RX, 4965287NX, 5579363NX, 5579363RX, Q612386, , Q621386, Q621386A C0023-SA, C0024-SA, 58005, 58007, BG1101, BG1102
	GESi-0019	ISX	CL-0003	G-0003	2871578, 1827739, 5579294, 1827739PEX, 2871578NX, 2871578RX, 5579294NX, 5579294RX, A029S844, 2274609, 2274609PE, 2274609PEX C0066-SA, C0067-SA, 58008, XN1104, GESi-0026
	GESi-0022	ISX	CL-0003 CL-0026	G-0003	1827310PEX, 629477, 1827310, 2274608, 2274608PE, 2274608PEX, 2871581, 5579293, 2871581NX, 2871581RX, 5579293NX, 5579293RX, Q629458, Q629477 C0033-SA, C0099-SA, 58008, 58011, XN1103, GESi-0053
	GESi-0029	ISM	CL-0003	G-0003	4352989NX, 4352989, 4965224, 5633693, 4352989RX, 4965224NX, 4965224RX C0022-SA, 58010, MN1003
	GESi-0035	ISL, ISC & PX8	CL-0002 CL-0026	G-0002	2871459, 629361, 2871482, 2880410, 2885918, 5579354, 2871459, 2871459NX, 2871459RX, 5579354NX, 5579354RX, Q629361 C0125-SA, 58012, CJ1205

Product Image	Part Number	Engine Model	Clamp Numbers	Gasket Numbers	OEM/Aftermarket Part Numbers
	GESi-0036	ISX	CL-0003	G-0003	5283286, 5271529, 5295609, 5579295, 2510616C91, 2510795C91, 5011031R91, 5283286NX, 5295609NX, 5295609RX, 5579295NX, 5579295RX, 1906311, 1906311PE, 1906311PEX, 2274611, 2274611PE, A041D448, A034R145, A064C007, 5012834R1, A043X536 C0107-SA, C0154-SA, C0159-SA, 58014, XN1107, GESi-0059
	GESi-0044	ISC	CL-0002	G-0002	3103617, 619496, 619733, 3976606, 3978026, 3978028, 3999661, 3999662, 061794A0A, 3976606NX, 3978026NX, 3999661NX, Q617788, Q617940, Q617940A, Q61925A, Q619495, Q619495A, Q619496, Q619725, Q619725A, Q619733 C0026-SA, 58009, CJ1202
	GESi-0054	ISX	CL-0003	G-0003	5295604, 5283283, 5579296, 5283283NX, 5295604NX, 5295604RX, 5579296NX, 5579296RX, A041D452 C0134-SA, 58031, 58036, XN1106
	GESi-0055	ISB	CL-0001	G-0001	2871461, 629355, 3618711, 5579365, 2871461NX, 2871461RX, 5579365NX, 5579365RX, Q629355 C0128-SA, 58028, BG1104
	GESi-0056	ISB & PX6	CL-0001 CL-0026	G-0001	2871462, 5579366, 2871462NX, 2871462RX, 55779366NX, 5579366NX, 5579366RX, A040M135 C0098-SA, C0161-SA, 58029, BG1103, BGF006
	GESi-0057	ISM	CL-0003	G-0003	5273093NX, 5273093, 5273093RX 58033
	GESi-0060	ISB	CL-0001 CL-0026	G-0001	5295603NX, 5295603, 5579367, 5295603RX, 5579367NX, 5579367RX C0161-SA, 58067

**** Due to industry changes, modifications and/or consolidations to aftermarket and/or OEM designs, please double-check your cross reference at www.dpfxfit.com to ensure accuracy and that you are using the most current information ****

Product Image	Part Number	Engine Model	Clamp Numbers	Gasket Numbers	OEM/Aftermarket Part Numbers
	GESi-0061	ISC	CL-0002	G-0002	5295606NX, 5295606, 5579357, 5295606RX, 5579357RX, 2513396C1, 5011153R1, 5011153R91, A045G339 C0136-SA , C0335-SA , 58012 , 58030 , LJ1207
	GESi-0067	ISX	CL-0010	G-0010	2134929, 2134929NX, 2134929PE, 2134929RX C0320-SA , 58092 , MQ0711
	GESi-0071	ISX	CL-0010	G-0010	2516807C91, 2131533, 2131533PEX, 2088082X, 2131533PE, 2520606C91, 5011521R91, 2274612PEX, A055H506 C0316-SA , C0325-SA , 58069 , MQ0710
	GESi-0074	ISX	CL-0002	G-0002	5295605NX, 5295605, 5306969, 5579356, 5295605RX, 5579356NX, 5579356RX C0153-SA , 58035 , LJ1206
	GESi-0075	ISX	CL-0003	G-0003	9199KDC
	GESi-0076	ISB	CL-0001	G-0001	5295607NX, 5295607, 5579368, 5295607RX, 5579368NX, 5579368RX C0164-SA , 58077 , BGF007
	GESi-0077	MX-13	CL-0003	G-0003	1900626PE, 1900626, 1900626PE, 1900626PEX, A041D451 C0155-SA , 58065 , MN1104
	GESi-0078	ISX, X15 & X12	CL-0010	G-0010	4394577, 5579297, 5509714, 4394577NX, 4394577RX, 5579297NX, 5579297RX, A55B953, A064C013, 2522529C91, CM12522529C91, 2520173C1, CM1252017C31, 5633757, 2078587X, 2078587XS C0310-SA , 58081 , XQ0710

Product Image	Part Number	Engine Model	Clamp Numbers	Gasket Numbers	OEM/Aftermarket Part Numbers
	GESi-0086	ISB 6.7	CL-0009	G-0009	4394227, 4394227NX, 4394227RX, A054M203, 2072898X, 2072898XS, 5579369, 5579369RX, A064B957, 3332017532 C0324-SA , 58277 , BJB514
	GESi-0092	X15 & X12	CL-0010	G-0010	4395011, 4395011NX, 4395011RX, A055R125, 5579299, 5579299RX, A064C118, 33068175700 C0319-SA , XQ0711
	GESi-0093	L9, B6.7L	CL-0009	G-0009	4394579, 4394579NX, 4394579RX, A055B959, 2064075X, 2064075XS, 5579371, 5579371RX, A064B961, 434579CUM C0329-SA , 58268 , BJ0710
	GESi-0094	L9, B6.7L	CL-0009	G-0009	4395009, 4395009NX, 4395009RX, A055R127, 5579376, 5579376RX, A064B971 C0321-SA , 58201 , BJ0711
	GESi-0096	L9	CL-0009	G-0009	A055B950, 4394578, 5579360, 5579360RX, 2067748X C0322-SA , 58203 , BJ0716
	GESi-0099	L9 & B6.7L	CL-0009	G-0009	4394228, 4394228RX, A068N102, A054M210, 2082341X, 2082341XS, 5579370, 5579370RX, 5579370NX, A064B959 C0352-SA , 58276 , BJ0712
	GESi-0100	L9	CL-0009	G-0009	4395010, 4395010RX, 5579361, 5579361RX, A055R128, A064B996 BJ0716

****Due to industry changes, modifications and/or consolidations to aftermarket and/or OEM designs, please double-check your cross reference at www.dpfxfit.com to ensure accuracy and that you are using the most current information****

Product Image	Part Number	Engine Model	Clamp Numbers	Gasket Numbers	OEM/Aftermarket Part Numbers
	GESi-0101	B6.7	CL-0009	G-0009	4394580, 4394580RX, A055B965, 5579372, 5579372RX, A064B963, 3D024186470 C0344-SA, 58319, BJB515
	GESi-0102	B6.7	CL-0009	G-0009	4395139, 4395139RX, 5579379, 5579379RX, A056D470, A064B97 C0362-SA, 58281, BJB518
	GESi-0103	B6.7	CL-0009	G-0009	4395008, 4395008RX, 5579375, 5579375RX, A055R126, A064B969
	GESi-0106	X15 & X12	CL-0010	G-0010	4394772, 4394772NX, 4394772RX, 5418493, 5418493NX, 5418493RX, 5509715, 5509715NX, 5509715RX, 5579298, 5579298NX, 5579298RX, 5633758, A054X763, A059P098, A064C015, A064F958 58363, XQ0713
	GESi-0108	X15 & X12	CL-0010	G-0010	3403870XS, 4394979, 4394979NX, 4394979RX, 5418494, 5418494NX, 5418494RX, 5509717, 5633708, 5633708CUM, 5633708NX, 5633708RX, 5633760, 5633760CUM, 5633760NX, 5633760RX, A055T677, A059P101, A064F960 58290, XQ0712
	GESi-501	ISC & ISL	CL-0002	G-0002	4965284NX, 5287496NX, A035H295 58023, CJ0401
	GESi-502	ISM	CL-0003	G-0003	4965243NX, 5287191NX, A035G674, 5287191, 4965243 C0028-ID, 58015, MN0402
	GESi-503	ISX	CL-0003	G-0003	2888249NX, 4969542NX, 4965317NX, A030W858, 2888249, 4969542, 4965317 C0060-ID, 58025, XN0504

Product Image	Part Number	Engine Model	Clamp Numbers	Gasket Numbers	OEM/Aftermarket Part Numbers
	GESi-504	ISM	CL-0003	G-0003	4965223NX, 5287521, A035H536 58024, MN0403
	GESi-505	ISX	CL-0003	G-0003	2888248, 4965225NX, A030W857 58026, XN0501
	GESi-506	ISX	CL-0003	G-0003	4965304NX, 2888247NX, A035W856 58027, XN0502
	GESi-507	ISB	CL-0001	G-0001	5287480NX, 4965285NX, A035H236 58022, BG0401
	GESi-508	ISX	CL-0002	G-0002	Q61949A, 3103618, 3978025, 3999660, Q619723, 3999660NX C0034-ID, 58042
	GESi-509	ISC & ISL	CL-0002 CL-0007	G-0002 G-0007	2871923NX, A029B190, 26326120259, 2871923, 2871773, 2871773NX, 2871469, 2871469NX C0137-ID, 58059, CJ0405
	GESi-510	ISC & ISL	CL-0002 CL-0007	G-0002 G-0007	2880589NX, 2880589, 4353303, 4353303NX, A029S790, A047V504, 5302636, 5302636NX, A042L841 C0142-ID, C0228-ID, 58061, 58216, CJ0406, LJ0429

****Due to industry changes, modifications and/or consolidations to aftermarket and/or OEM designs, please double-check your cross reference at www.dpfxfit.com to ensure accuracy and that you are using the most current information****

Product Image	Part Number	Engine Model	Clamp Numbers	Gasket Numbers	OEM/Aftermarket Part Numbers
	GESi-511	ISX	CL-0003 CL-0005	G-0003 G-0005	2880506, 2880385, 2880506NX, 2880385NX, A029U527 C0112-ID, 58040, XN0615
	GESi-512	ISX	CL-0003 CL-0005	G-0003 G-0005	2880165NX, A029A324, 2880165, 2880165RX 58219, XN0636
	GESi-513	ISX	CL-0003 CL-0005	G-0003 G-0005	1837303PE, 1978264PE, 2871577NX, 4353221NX, 5298349NX, 2871483, 2871484 C0070-ID, 58062, XN0610, XN0620
	GESi-514	ISX	CL-0003 CL-0005	G-0003 G-0005	4969721NX, 2888262NX, 2880259NX, 4969719NX, A030X734, Q62230, 4969721, 2606971, 4936734NX, 2607044C91, 2888262, 4969721NX, 4936734, 2606932C1, 2880259, Q620939, 4965079, Q620929
	GESi-515	ISC	CL-0002 CL-0007	G-0002 G-0007	5287491, 5287491NX, 5287491RX, A035H299, 4965352, 4965352NX, Q621560 C0117-ID, C0117ID, 58052, CJ0403
	GESi-516	ISM & ISL	CL-0003 CL-0005	G-0003 G-0005	5287519, 5287519NX, 5287519RX, A035H544, 4969719, 4969719NX, Q622229, 4965054, 4965054NX, Q620565, 2606987C91, 3817962C91 C0017-ID, C0017ID, 58039, MN0401
	GESi-518	ISC & ISL	CL-0002 CL-0008	G-0002 G-0008	4353304, 4353304RX, A047V505, 5302769, 5302760NX, A042M251 C0365-ID, 58095, LJ0413
	GESi-524	ISX	CL-0003 CL-0006	G-0003 G-0006	4353264, 4353264NX, 4353264RX, 5309560, 5309560NX, 5309560RX, 2510794C91, 2510615C92, A047V463 C0152-ID, 58021, XN0618

Product Image	Part Number	Engine Model	Clamp Numbers	Gasket Numbers	OEM/Aftermarket Part Numbers
	GESi-528	ISB & PX6	CL-0001 CL-0007	G-0001 G-0007	2871571, 2871571NX, 2871571RX, 4353324RX, 4353324, 4353324NX, 2871760, 2871760RX, 2871467, 287146NX, 2871467RX, 5308480, 5308480NX, 5287262, 4353326NX, 4353326RX, 5301062
	GESi-529	ISX	CL-0003 CL-0005	G-0003 G-0005	2880502, 2888257 58099, XN0641
	GESi-530	ISB 6.7 & PX6	CL-0001 CL-0008	G-0001 G-0008	2880520, 2880520NX, 2880520RX
	GESi-531	ISM	CL-0003	G-0003	4969846NX, 5287522NX, A68040903214 58058, MN0406
	GESi-532	ISB	CL-0001 CL-0007	G-0001 G-0007	4353323
	GESi-533	ISL9 & PX-9	CL-0002 CL-0007	G-0002 G-0007	4353289, 4353289NX, 4353289RX, 5300556, 5300556NX, 5287368, 5287368NX, 5308482, 5308482NX, 4387170, 4387170NX C0176-ID, 58078, LJ0426
	GESi-536	ISX	CL-0003 CL-0006	G-0003 G-0006	5289745NX, 5289745RX, 5289745 C0332-ID, 58068

****Due to industry changes, modifications and/or consolidations to aftermarket and/or OEM designs, please double-check your cross reference at www.dpfxfit.com to ensure accuracy and that you are using the most current information****

Product Image	Part Number	Engine Model	Clamp Numbers	Gasket Numbers	OEM/Aftermarket Part Numbers
	GESi-537	ISX	CL-0003 CL-0006	G-0003 G-0006	5274535RX, 5274535, 5274535NX 58066
	GESi-538	ISC & ISL	CL-0002 CL-0007	G-0002 G-0007	2880498, 2880498NX, 2880498RX, A029S731 58208, CJ0421
	GESi-543	ISC & ISL	CL-0002 CL-0007	G-0002 G-0007	2880153, 2880153NX, A029B836 58211, CJ0424
	GESi-544	ISC & ISL	CL-0002 CL-0008	G-0002 G-0008	2880512, 2880512NX, 2880512RX, A029W349, 2871468, 2871468NX, Q629359 C0224-ID, 58098, CJ0404
	GESi-545	ISX	CL-0003 CL-0005	G-0003 G-0005	4353285, 4353285NX, 4353285RX, A047V485, 5298345, 5298345NX, A041P423, 4329543, 4329543NX, A045X393, 1912730, 1912730PE, 1912730PEX, 1978269, 1978269PE, 1978269PEX, A047V566, 1998412, 1998412PE, 1998412PEX C0229-ID, 58080, XN0625
	GESi-546	ISX	CL-0003 CL-0005	G-0003 G-0005	4329542, 4329542NX, 4353284, 4353284NX, 4353284RX, 5287100, 5287100NX, 5298350, 5298350NX, A047V484, 5298350RX, 4353284RXCUM C0163-ID, C0187-ID, 58079, MN0608, XN0624
	GESi-547	ISX	CL-0003 CL-0005	G-0003 G-0005	2880582NX, 4353249, 2880582RX, 1837300PE, 4353249NX, 5286910NX, 5298340NX, 1837300PEX, 4353249RXCUM, 2880582RXCUM, 4353249RXCUM, 2880582, 435324RX (SUPERSEDED PARTS 2880582NX, 5298340NX), A29U831, 4353249RX, A047V447, 5298340, A041P368, 5286910, A035E403, 1978266PE C0111-ID, C0115-ID, C0127-ID, C0303-ID, 58041, XN0613, XN0631
	GESi-548	ISX	CL-0003 CL-0005	G-0003 G-0005	2888261, 2888261NX, 2888261RX, A030X733, 4969718, 4969718NX, Q622228, 4965053, 4965053NX, Q620564, 2596690C91 C0010-ID, C0010ID, C0071-ID, C0071ID, 58048, XN0505

Product Image	Part Number	Engine Model	Clamp Numbers	Gasket Numbers	OEM/Aftermarket Part Numbers
	GESi-550	ISB	CL-0001 CL-0007	G-0001 G-0007	5287474, 5287474NX, 5287474RX, A035H173, 4965338, 4965338NX, 4965338RX, Q621546 C0119-ID, C0119ID, 58053, BG0402
	GESi-551	ISX	CL-0003 CL-0005	G-0003 G-0005	2880174, 2880174NX, 2880174RX C0114-ID, 58018, XN0614
	GESi-552	ISX	CL-0003 CL-0006	G-0003 G-0006	2880505NX, 4353251, 5300526, 2880505, 2880505RX, 5300526RX, 5300526NX, 4353251RX C0106-ID, C0211-ID, 58019, XN0612, XN0622
	GESi-553	ISX	CL-0003 CL-0005	G-0003 G-0005	4328760, 4328760NX, 4353257, 4353257NX, 4353257RX, 5302735, 5302735NX C0126-ID, 58056, XN0621
	GESi-556	ISC, ISL9, PX8	CL-0002 CL-0007	G-0002 G-0007	2885940, 2885940NX, 2885940RX, A030D523 C0158-ID, 58063, CJ0407
	GESi-558	ISX	CL-0003 CL-0006	G-0003 G-0006	4352289RX, 5284269NX, 5284269RX, 5284269, 4352289, 4352289NX 58075
	GESi-559	ISX & N13	CL-0003 CL-0006	G-0003 G-0006	4353274, 4353274NX, 4353274RX, A047V475, 5313770, 5313770NX, A044L216, 2510787C91, 2510787C92, 2510777C91 C0339-ID, 58214, XN0632

****Due to industry changes, modifications and/or consolidations to aftermarket and/or OEM designs, please double-check your cross reference at www.dpfxfit.com to ensure accuracy and that you are using the most current information****

Product Image	Part Number	Engine Model	Clamp Numbers	Gasket Numbers	OEM/Aftermarket Part Numbers
	GESi-560	MX-13	CL-0003 CL-0005	G-0003 G-0005	1912726, 1912726PE, 1949999, 1949999PE, 1949999PEX, 1978265, 1978265PE, A047V565 58079 , C0163-ID , MN0608
	GESi-561	ISX	CL-0003 CL-0005	G-0003 G-0005	4353250, 4353250NX, 4353250RX, 5298344, 5298344NX, 5298344RX 58280
	GESi-563	ISB, QSB & PX9	CL-0007 CL-0009	G-0007 G-0009	4394601, 4394876, 4394876NX, 4394876RX, 4395106, 4395106NX, 4395106RX, 4395112, 4395112NX, 4395112RX, 5418478, 5418478NX, 5418478RX, A055P601, A056A967, A059N984, A059N985 2116695X, 2D006186398 58318 , 58327
	GESi-564	X12 & X15	CL-0006 CL-0010	G-0006 G-0010	4394855, 4394855RX, A055N645, 5509698, 5509698RX, A055N645, 4394756, 4394756NX, 4394756RX, A055J297, 2520174C1, CMI2520174C1 C0349-ID , 58312 , 58366 , XQ0461
	GESi-565	B6.9 & L9	CL-0008 CL-0009	G-0008 G-0009	4394859, 4394859NX, 4394859RX, A055N879, 2116818XS 58324
	GESi-566	68.3L ISC, ISL9 & PX8	CL-0002 CL-0008	G-0002 G-0008	2880631, 2880631NX, 2880631RX, A029U810
	GESi-567	X12 & X15	CL-0005 CL-0010	G-0005 G-0010	A057R544, 5417993, 5417993RX
	GESi-568	X12 & X15	CL-0005 CL-0010	G-0005 G-0010	4394906, 4394906NX, 4394906RX, 5509700, 5509700NX, 5509700RX, A055R708, A071V070, A074Z258 58372 , XQ0462

Product Image	Part Number	Engine Model	Clamp Numbers	Gasket Numbers	OEM/Aftermarket Part Numbers
	GESi-569	MX-13	CL-0006 CL-0010	G-0006 G-0010	2131526, 2131526PE, 2131526PEX, 2088094XS, A055H477 C0318-ID , 58070 , MQ0417
	GESi-570	B6.7	CL-0008 CL-0009	G-0008 G-0009	4394602, 4394602NX, 4394602RX, 4395107, 4395107NX, 4395107RX, 5418479, 5418479NX, 5418479RX, A055B981, A056A968, A059N985 C0369-ID , C0369ID , 58295
	GESi-571	ISC & ISL	CL-0008 CL-0009	G-0008 G-0009	A059N987, 5418481, 5418481RX, 2083389X
	GESi-572	B6.7 & L9	CL-0008 CL-0009	G-0008 G-0009	5418479, A059N985, 2468127XS, 2D3192302 C0369-ID , C0369ID , 58295
	GESi-601	ISL-G	CL-0002	G-0002	4969771, 4969771NX, 4969771RX, 4969770, 4969770NX, 4969770RX, Q621799 C0101-ID , 58045

****Due to industry changes, modifications and/or consolidations to aftermarket and/or OEM designs, please double-check your cross reference at www.dpfxfit.com to ensure accuracy and that you are using the most current information****



Product Image	Part Number	Engine Model	Clamp Numbers	Gasket Numbers	OEM/Aftermarket Part Numbers
	GESi-0011	MP7	CL-0019	G-0019	20231111, 20869859, 20992181, 21048577, 21246955, 21804785, 21817835, 85000899, 85003793, 85125682 C0049-SA, 82008, VN1201
	GESi-0012	ISX	CL-0003	G-0003	4388411, 4965305, 4965322, 4969703, 5283799, 5288411, 5297989, 5579292, 20970295, 21850651, 85001366, 4388411NX, 4388411RX, 4965129D, 4965305NX, 4965305RX, 4969703NX, 4969703RX, 5283799NX, 5297989NX, 5297989RX, 4388411RX, 5283799, 4388411NX C0007-SA, C0021-SA, 82002, 82020, XN1102, VN1203
	GESi-0015	MP7	CL-0019	G-0019	21395825, 85124613 C0095-SA, 82014, VN1207
	GESi-0024	D11, D13, D16	CL-0004	G-0004	Q621938, 20864127, 21850658, 85000726, Q621938 C0006-SA, 82006, VQ1202, XN1102
	GESi-0025	D13, MP8	CL-0022	G-0022	21212426, 21212431, 21212428, 21212429, 21212431, 21415912, 21756428, 21756429, 22413830, 22413832, 22810502, 22810503 C0064-SA, 82010, VN1206
	GESi-0032	MP7, MP8	CL-0003	G-0003	20864558, 21905492, 85001353, 85001367, 20864558 C0050-SA, 82009, VN1205
	GESi-0041	MP8	CL-0004	G-0004	85000725, 20864316, 21851879, 21905428 C0044-SA, 82011, VQ1204

****Due to industry changes, modifications and/or consolidations to aftermarket and/or OEM designs, please double-check your cross reference at www.dpfxfit.com to ensure accuracy and that you are using the most current information****

OEM Durability & Performance with Aftermarket Affordability



EXTENSIVE PRODUCT RANGE & PROMPT DELIVERY

COATED IN-HOUSE WITH PLATINUM GROUP METALS

MANUFACTURED IN NORTH AMERICA



INCLUDES OEM QUALITY CLAMPS & GASKETS!

Product Image	Part Number	Engine Model	Clamp Numbers	Gasket Numbers	OEM/Aftermarket Part Numbers
	GESi-0050	MP7, MP8, D11, D13	CL-0019	G-0019	2276198, 21393279, 21395827, 21471269, 22342601, 22761989, 85124653 C0165-SA, 82013, VN1209
	GESi-0063	MP7, MP8, D11, D13	CL-0023 CL-0024	G-0023 G-0024	21716414, 21716416, 21775798, 21775802, 22069507, 22936980, 23105393, 23108407, 23108408, 23135528, 85013300, 85021740, 7421716414, 7421716416, 7421716419, 7423135543, 7485013298, 7485013301, 21775793, 22776213, 22776214, 7421775794, 7421775800, 7485013305, 85013304 C0307-SA, 8AI002, 8AI004, VN1212
	GESi-521	D13, MP8, D16 & MP10	CL-0004	G-0004	20864129, 21850645, 85001355, Q619723, Q621417
	GESi-522	D11, MP7, D13, MP8, D16 & MP10	CL-0005 CL-0022	G-0022 G-0033	21756505, 21212405 C0097-ID, 82018, VNB407
	GESi-527	D11, MP7, D13, MP8, D16 & MP10	CL-0005 CL-0022	G-0022 G-0033	21756506, 21212407 C0075-ID, 82018, VNB406
	GESi-534	MP7	CL-0003	G-0003	20863840, 21850643, 85000777, 85001356 C0008-ID, 82016, VN0401
	GESi-554	D13, MP8, D16 & MP10	CL-0004	G-0004	20864132, 85000779, 850001354, 21850647 C0116-ID, C0116ID, 82019, VN0603
	GESi-555	D13, MP8 & D16, MP10	CL-0005 CL-0022	G-0022 G-0033	21212414, 21756508, 21756509 82023, VN0608



Whether you want to maximize and save fuel, perform preventive maintenance, or meet current environmental regulations, we provide you with feedback and advice that's easy to understand and follow.

Due to industry changes, modifications and/or consolidations to aftermarket and/or OEM designs, please double-check your cross reference at www.dpfxfit.com to ensure accuracy and that you are using the most current information




OEM Durability & Performance with Aftermarket Affordability



EXTENSIVE PRODUCT
RANGE & PROMPT
DELIVERY



COATED IN-
HOUSE WITH
PLATINUM GROUP
METALS



MANUFACTURED
IN NORTH
AMERICA



**INCLUDES OEM QUALITY
CLAMPS & GASKETS!**



Product Image	Part Number	Engine Model	Clamp Numbers	Gasket Numbers	OEM/Aftermarket Part Numbers
	GESi-0003	MAXX-FORCE 7 & DT	NOT REQUIRED	G-0025 G-0026	2517331C91, 82003341, 2593981C91, 2593981R91, 2594022C91, 2604873C91, 2605123C91, 5010836R91, 5010847R1, 5010847R91, 5011143R91, A00383921 C0039-SA , C0113-SA , 65005 , 65837 , MC0508 , MJ0824 , MJ1206 , MJ1226
	GESi-0004	MAXX-FORCE 7 & DT	NOT REQUIRED	G-0025 G-0026	2594356C91, 2594356R91, 5010834R91 C0042-SA , 65013 , 65837 , MK1208 , MK1228
	GESi-0005	MAXX-FORCE	CL-0020	G-0020	5010832R91, 25494131C91, 2594131C91, 2594131R91, A00574039 C0020-SA , 65017 , MJ1222
	GESi-0006	MAXX-FORCE 7 & DT	CL-0020	G-0020	2594165C91, 2594165R91, 5010830R91 C0047-SA , 65018 , 65835 , MK1223
	GESi-0007	MAXX-FORCE 9	NOT REQUIRED	G-0025 G-0026	2604870C91, 82002756, 2604870R91, 2605796C91, 2611630C91, 5010846R1, 5010852R1, A00317258 C0078-SA , 65009 , 65837 , MN1029
	GESi-0008	MAXX-FORCE 9	CL-0020	G-0020	2604430C91, 82002806, 2604430R91, 2605039C91, 2612512C91, 2612521C91, 2613113C91, 3712647C91, 5010843R1, 5010853R1, 5012831R1, A00420195 C0048-SA , 65010 , 65835 , MC0502 , MN1027
	GESi-0020	MAXX-FORCE 13	CL-0021	G-0021	2604046C91, 232717, 2604830C91, 2604830R91, 3859691C94, 5010845R1, CP232717 C0079-SA , 65011 , 1M0403 , 1N1204 , 1N1205

****Due to industry changes, modifications and/or consolidations to aftermarket and/or OEM designs, please double-check your cross reference at www.dpfxfit.com to ensure accuracy and that you are using the most current information****

Product Image	Part Number	Engine Model	Clamp Numbers	Gasket Numbers	OEM/Aftermarket Part Numbers
	GESi-0021	MAXX-FORCE 13	CL-0021	G-0021	2603961C91, 2604823C91, 2604823R91, 3859549C93, 3886127C91, 3930745C91, 5010844R1 C0091-SA, 65014, 1M0402, 1N1205
	GESi-0049	MAXX-FORCE 7 & DT	CL-0020	G-0020	2605124C1, 2605837C1, 5010850R1 C0144-SA, 65023, 65835, MJ0820
	GESi-0084	MAXX-FORCE DT9 & DT10	CL-0020	G-0020 G-0025	2514351C91, 2594363C91, 5010838R1, 5010838R91 C0146-SA, C0146SA, 65024, MN1025
	GESi-519	MAXX-FORCE 13	G-0026	G-0007 G-0021	2604039C91, 3865483C93, 3869133C93, 5010811R91, IP23265 C0105-ID, 65020, 1M0403
	GESi-520	MAXX-FORCE 13	CL-0007 CL-0021	G-0007 G-0021	2603960C91, 5010812R91 C0104-ID, 65021, 1M0402
	GESi-525	MAXX-FORCE 7	CL-0020	G-0020	2605332C91, 5011047R91 C0051-ID, 65027, MC0502
	GESi-526	MAXX-FORCE	CL-0020 CL-0025	G-0020	2594140C9, 2594179C91 C0019-ID, 65026, MC0501
	GESi-535	MAXX-FORCE 11 & 13	CL-0003 CL-0005	G-0003 G-0005	2596666C91

Product Image	Part Number	Engine Model	Clamp Numbers	Gasket Numbers	OEM/Aftermarket Part Numbers
	GESi-539	MAXX-FORCE 7	CL-0025	G-0025	2596407C92, 5011122R91 C0069-ID, 65028, MC0503
	GESi-540	MAXX-FORCE	CL-0025	G-0025	2595714C91, 5011120R91 C0081-ID, 65030, MC0504
	GESi-541	MAXX-FORCE	CL-0020 CL-0025	G-0020	2594146C91, 3811202C95, 3811190C95, 2594140C91 C0019-ID, 65026, MC0501
	GESi-542	MAXX-FORCE 7	NOT REQUIRED	G-0025	2605126C1, 2605128C1, 2605802C1, 5011044R1 C0138-ID, 65022, MC0511


****Due to industry changes, modifications and/or consolidations to aftermarket and/or OEM designs, please double-check your cross reference at www.dpfxfit.com to ensure accuracy and that you are using the most current information****

Warranty/Defective Merchandise

- ✕ All DPFxFIT™ aftertreatment products are covered by a limited 3-year, unlimited mileage warranty.
- ✕ All DPFxFIT™ accessory products (clamps, gaskets & sensors) are covered by a limited 1-year warranty.
- ✕ All warranty claims are subject to inspection by a GESi® representative.
- ✕ Proof of purchase within 3-year warranty period is required for all warranty claims.



OEM Durability & Performance with Aftermarket Affordability



INCLUDES OEM QUALITY CLAMPS & GASKETS!

Product Image	Part Number	Engine Model	Clamp Numbers	Gasket Numbers	OEM/Aftermarket Part Numbers
	GESi-0013	S60	CL-0019	G-0019	23537225, 6804908692, 6804910294, 6804910594, A6804908692, A6804910294, A6804910594, E6804910594, EA6804908692, EA6804910294, EA6804910594, RA6804908692 C0002-SA, 35002, DN1501
	GESi-0027	DD13 & DD15	CL-0017	G-0017	A6804910794, 4 903492, 14907192, 6804910794, A0004903492, A0014904092, A0014907192, A0014907792, EA0014904092, EA0014907792, EA0014907192, EA6804910794, EA6804913694, RA0014904092, RA0014907192, RA6804910794, DDEEA6804910794, DDERA6804910794, DDEEA0014907192, DDERA0014907192, 680491369 4, DDERA6804913694, RA6804913694, A6804913694 C0029-SA, C0080-SA, 35008, 82010, DQ1202, C17-0067
	GESi-0028	MB OM926	CL-0015	G-0015	A6804904392, 680490392, 6804905792, 6804906192, 6804910094, 6804910097, 6804915794, 6809408792, A6804905792, A6804906192, A6804908792, A6804910094, A6804915794, R23537521, RA6804908792, RA6804910097 C0054-SA, 35006, DG1204
	GESi-0040	S50	CL-0002	G-0002	23535827, E23535827 C0089-SA, DJ1207
	GESi-0051	DD13 & DD15	CL-0016 CL-0018	G-0016	A0001403492, A0004903792, A0014903492, A0014903592, A6804903792, A6804910894, A6804913494, A6804913594, EA0014903492, EA0014903592, EA0149007792, EA6804910894, RA0004903792, RA0014903492, RA0014903592, RA6804903792 C0080-SA, 35007, DJ0806
	GESi-0052	DD13 & DD15	CL-0016 CL-0018	G-0016	A6804910494, 6804910494, A000490369, A0004903692, A6804903692, EA6804910494, RA0004903692, RA6804903692 C0088-SA, 35011, DJ1005
	GESi-0081	DD13 & DD15	CL-0016 CL-0018	G-0016	A0014907692, RA0014907692, EA0014907692, RA6804914194 C0380-SA, 35021, DJ0813

****Due to industry changes, modifications and/or consolidations to aftermarket and/or OEM designs, please double-check your cross reference at www.dpffit.com to ensure accuracy and that you are using the most current information****

Product Image	Part Number	Engine Model	Clamp Numbers	Gasket Numbers	OEM/Aftermarket Part Numbers
	GESi-0097	DD13, DD15, DD16	CL-0028 CL-0029	G-0034	A0024908392, EA0024908392, RA0024908392, EA0074908214, A0074908214 DQ0919
	GESi-0111	DD5 & DD8	CL-0011 CL-0032	G-0011	A0014908892, DDE A0014908892, DDE EA0014908892, DDE RA0014908892, EA0014908892, RA0014908892, A0024905792, DDE A0024905792, DDE EA0024905792, DDE RA0024905792, EA0024905792, RA0024905792 DJ0715

****Due to industry changes, modifications and/or consolidations to aftermarket and/or OEM designs, please double-check your cross reference at www.dpfxfit.com to ensure accuracy and that you are using the most current information****

Order Placement

Orders may be placed in the following ways:

Online Portal	Email	Phone
https://portal.dpfxfit.com	orders@gesi.us	1-888-758-4374
To register to get set up on the DPFxFIT™ portal, please email orders@gesi.us	Please ensure that a P.O number is clearly noted on the order/ email	Orders may be placed by telephone as long as a P.O number is provided.

All orders will be processed on a first in - first out basis.

We accept payment as follows:

- ✗ (ACH) Automated Clearing House Electronic Payments (USD funds for US accounts only)
- ✗ (EFT) Electronic Funds Transfer (CAD funds for Canadian accounts only)
- ✗ Credit card (where terms are not applicable)
- ✗ Company cheque (upon credit approval)
- ✗ Wire transfers



←
**SCAN OUR
QR CODE
&
FIND YOUR
PART
TODAY**
↓





OEM Durability & Performance with Aftermarket Affordability



EXTENSIVE PRODUCT
RANGE & PROMPT
DELIVERY



COATED IN-
HOUSE WITH
PLATINUM GROUP
METALS



MANUFACTURED
IN NORTH
AMERICA



**INCLUDES OEM QUALITY
CLAMPS & GASKETS!**



Product Image	Part Number	Engine Model	Clamp Numbers	Gasket Numbers	OEM/ Aftermarket Part Numbers
	GESi-0014	C13 & C15	CL-0012	G-0012	290-0045, 301-7856, 10R-6088 46002, CQ1702
	GESi-0038	C13 & C15	CL-0013	G-0013	304-7502, 304-7519, 10R-7056 46005, CQ1501
	GESi-0039	C13 & C15	CL-0013	G-0013	291-8519, 1733481, 2918519, 2939990, 2948694, 10R-6089, 20R-8020, 294-8694 46003, CQ1704
	GESi-0042	C9 & C7	CL-0012	G-0012	291-8515, 10R-6087, 294-8692, 309-6991 CN1505
	GESi-0045	C9	CL-0014	G-0014	261-2318, 220-6054, 250-0630, 264-1556 C0011-SA
	GESi-0085	C7 & C9	CL-0012	G-0012	291-8514, 294-8691
	GESi-0095	C12	CL-0003	G-0003	9099MD

****Due to industry changes, modifications and/or consolidations to aftermarket and/or OEM designs, please double-check your cross reference at www.dpfxfit.com to ensure accuracy and that you are using the most current information****



BETTER PERFORMANCE | BETTER SERVICEABILITY

- ✕ Greatest application coverage available in the aftermarket
- ✕ Larger filters resulting in reduced back pressure in certain applications
- ✕ Serviceable units available with included V-band clamps for ongoing maintenance & cleanings
- ✕ Stainless steel construction, yet lighter weight than OEM



	Product Image	Part Number	Engine Model	Clamp Numbers	Gasket Numbers	OEM/Aftermarket Part Numbers
FORD		GESi-0056	F650	CL-0001 CL-0026	G-0001	2871462, 5579366, 2871462NX, 2871462RX, 55779366NX, 5579366NX, 5579366RX, A040M135 C0098-SA, C0161-SA, 58029, BG1103, BGF006
		GESi-0060	F750	CL-0001 CL-0026	G-0001	5295603NX, 5295603, 5579367, 5295603RX, 5579367NX, 5579367RX C0161-SA, 58067
		GESi-0065	2007-2010 F250/F350	NOT REQUIRED	G-0027	9C3Z5H221A, 9C3Z-5H221-A, AP649007
		GESi-0069	2007-2010 F250/F350/ F450 SUPERDUTY	NOT REQUIRED	G-0027	9C3Z5H221B, 9C3Z-5H221-B, 7C3Z5H221CA, 7C3Z-5H221-CA, 649001
		GESi-0082 *	2012, 2017-2019 6.2L/6.7L POWERSTROKE (CAB & CHASSIS) CUT OUT / WELD IN UNIT	NOT REQUIRED	NOT REQUIRED	CC3Z-5H270-B, HC3Z-5H270-C, DC3Z-5H270-A, DC3Z-5H270-D, HC3Z-5H270-B
		GESi-0083 *	2012, 2017-2019 6.2L/6.7L POWERSTROKE (PASSENGER) CUT OUT / WELD IN UNIT	NOT REQUIRED	NOT REQUIRED	HC3Z-5H270-A, CC3Z-5H270-A
		GESi-549 *	2012, 2017-2019 6.2L/6.7L POWERSTROKE CUT OUT / WELD IN UNIT	NOT REQUIRED	NOT REQUIRED	DC3Z-5H270-C, DC3Z-5H270-A

*This unit is not a direct OEM replacement. The aftermarket unit (DOC / DPF) requires professional installation including removal of OEM unit and welding of new replacement unit.

Due to industry changes, modifications and/or consolidations to aftermarket and/or OEM designs, please double-check your cross reference at www.dpfxfit.com to ensure accuracy and that you are using the most current information

	Product Image	Part Number	Engine Model	Clamp Numbers	Gasket Numbers	OEM/Aftermarket Part Numbers
DODGE		GESi-0064	2007-2012 RAM 2500/3500	NOT REQUIRED	G-0025	68035060AA, 68035060AC, 68035061AB, 649002
GMC		GESi-0070*	2017-2024 6.6L DURAMAX CUT OUT / WELD IN UNIT	NOT REQUIRED	NOT REQUIRED	84614676

*This unit is not a direct OEM replacement. The aftermarket unit (DOC / DPF) requires professional installation including removal of OEM unit and welding of new replacement unit.
Due to industry changes, modifications and/or consolidations to aftermarket and/or OEM designs, please double-check your cross reference at www.dpfxfit.com to ensure accuracy and that you are using the most current information

DID YOU KNOW

The diesel emission system is quite simple but the failures that occur upstream are more complicated. It is critical that ALL fuel, air, turbo, cooling & oil components are kept in optimum operating condition at all times to avoid issues with the emission system parts. Using inferior engine oil that doesn't comply with the latest standards for diesel engines and failing to comply with OE service and preventative maintenance recommendations will lead to increased cost long-term and ultimately downtime.

Do you know your fleet's true Cost per Mile?

Tired of chasing the 'lowest' price to find out it costs you more in the long run? Take advantage of DPFXFIT™'s aftermarket affordability with OEM performance.



KNOW WHAT YOU'RE GETTING INTO WITH DPFXFIT™

Understanding the true Cost per Mile (CPM) for your aftertreatment systems, including your Diesel Particulate Filter (DPF) and Diesel Oxidation Catalyst (DOC) is key for optimal fleet management. **Avoid the lengthy search, administration and uncertainty of a re-manufactured model. Make the DPFXFIT™ upgrade today.**

HOW MUCH WILL ALL OF THIS REALLY COST YOU?



	Product Image	Part Number	Engine Model	Clamp Numbers	Gasket Numbers	OEM/Aftermarket Part Numbers
ISUZU		GESi-0030	6HK1	NOT REQUIRED	G-0031	897608057, 8976080573, 8-97608-057-3, 8-976080-57-0, 897608057, 897608057-0, 897608057-3, 897608057-4, 8976080574, 8-97608-057-4, 97608057, 2-9408B-200-0, 2-9408B200-0, 29408B2000, 9408B200 C0053-SA, 39000, SG0801
		GESi-0073	6HK1	NOT REQUIRED	G-0031 G-0032	898155142, 898155142-0, 8981551410, 29408B1001 C077-SA, 39001, SG0802
		GESi-0079	REACH	NOT REQUIRED	G-0030 G-0032	898147-066-0, 898147-066-6, 8-98147066-0, 8981470660, 898147066, 8-98147-066-0, 2-9408B-300-0, 2-9408B300-0, 29408B3000, 2-9408B-061-0, 898205061 (Assembly) SC0703, SG0801
		GESi-0098	4HK1	NOT REQUIRED	G-0031 G-0032	898287808, 8982878080, 8-98287-808-0, 8-98287808-0, 2-9408B-808-0, 2-9408B808-0, 29408B8080, 2-9408B-500-0 39004, C0309-SA, SG0803
HINO		GESi-0062	HINO JO8E	NOT REQUIRED	G-0029	S1805E0270, S1805E0281, S1850E0281 C0027-HF, 34603, JG1002
		GESi-0068	HINO JO8E	NOT REQUIRED	G-0028	S1850E0B00, 1507940, 174311690, S1805-E0B5, S1805E0B5, S1850-E0B00, S1850E0580 C0149-SA, 34602, JJB703
		GESi-0107	HINO	NOT REQUIRED	G-0028	S1805-E0C40, S1805EW020
		GESi-0109	HINO	NOT REQUIRED	G-0028	S1805E069, S1850E0741 C0326-HF, C0326HF

	Product Image	Part Number	Engine Model	Clamp Numbers	Gasket Numbers	OEM/Aftermarket Part Numbers
HINO		GESi-0110	HINO	NOT REQUIRED	G-0032 G-0039	18040-78090, 1804078090
MERCEDES BENZ/ FREIGHTLINER		GESi-0066	3.0L	NOT REQUIRED	NOT REQUIRED	9064900792, 9094900792, 68011959AA, 906.490.0792, A9064900792, A9064901592 56346

****Due to industry changes, modifications and/or consolidations to aftermarket and/or OEM designs, please double-check your cross reference at www.dpfxfit.com to ensure accuracy and that you are using the most current information****



Product Image	Part Number	OEM/Aftermarket Part Numbers	GESi Units
	CL-0001	2871861, 4965096, 2871857, Q187680, P238307 CL-1051 , VB2001 , 58824 , CL001 , X12C0-01040-VB	GESi-0018, GESi-0055, GESi-0056, GESi-0060, GESi-0076, GESi-507, GESi-528, GESi-530, GESi-532, GESi-550
	CL-0002	280-410, 2871858, 2871858, 4965086, 4965097, Q187681, 2871862, 4965072, 3977454, 3977894, P238308 CL-1052 , VB2002 , 58825 , CL002 , X12C0-01190-VB	GESi-0009, GESi-0017, GESi-0035, GESi-0040, GESi-0044, GESi-0061, GESi-0074, GESi-501, GESi-508, GESi-509, GESi-510, GESi-515, GESi-518, GESi-533, GESi-538, GESi-543, GESi-544, GESi-556, GESi-566, GESi-601
	CL-0003	2871863, 21445455, 1912710PE, 259663C1, Q187682, P238310, 2871859 CL-1053 , VB2003 , 65822 , CL004 , X12C0-01342-VB	GESi-0001, GESi-0002, GESi-0010, GESi-0012, GESi-0016, GESi-0019, GESi-0022, GESi-0023, GESi-0026, GESi-0029, GESi-0032, GESi-0033, GESi-0036, GESi-0053, GESi-0054, GESi-0057, GESi-0058, GESi-0059, GESi-0075, GESi-0077, GESi-0095, GESi-502, GESi-503, GESi-504, GESi-505, GESi-506, GESi-511, GESi-512, GESi-513, GESi-514, GESi-516, GESi-524, GESi-529, GESi-531, GESi-534, GESi-535, GESi-536, GESi-537, GESi-545, GESi-546, GESi-547, GESi-548, GESi-551, GESi-552, GESi-553, GESi-558, GESi-559
	CL-0004	21445458, 2871864, P238312, Q187683 CL-1054 , VB2004 , 82809 , CL005 , X12C0-01443-VB	GESi-0024, GESi-004, GESi-521, GESi-554
	CL-0005	5290118, 2880483, 90-0013, A029T535 CL-1055 , VB2005 , 35803 , CL040-K1 , X12C0-00588-VB	GESi-511, GESi-512, GESi-513, GESi-514, GESi-516, GESi-522, GESi-527, GESi-529, GESi-535, GESi-545, GESi-546, GESi-547, GESi-548, GESi-551, GESi-553, GESi-555, GESi-560, GESi-561, GESi-567, GESi-568
	CL-0006	2880213, LP34216, A029E742, 5304600 CL-1056 , VB2009 , 58829 , CL056 , X12C0-00638-VB	GESi-524, GESi-536, GESi-537, GESi-552, GESi-558, GESi-559, GESi-564, GESi-569
	CL-0007	3896337, 2880482, 21021852, FLTEC40VBS CL-1057 , VB2014 , 58810 , CL045 , X12C0-00475-VB	GESi-509, GESi-510, GESi-515, GESi-519, GESi-520, GESi-528, GESi-532, GESi-533, GESi-538, GESi-543, GESi-550, GESi-556, GESi-563

Product Image	Part Number	OEM/Aftermarket Part Numbers	GESi Units
	CL-0008	2880212, A029E741 CL-1058 , VB2028 , 58830 , CL058	GESi-518, GESi-530, GESi-544, GESi-565, GESi-566, GESi-570, GESi-571, GESi-572
	CL-0009	A056M545, 5417471 CL-1060 , VB2037 , 58843 , CL068 , X12C0-01289-VB	GESi-0086, GESi-0093, GESi-0094, GESi-0096, GESi-0099, GESi-0100, GESi-0101, GESi-0102, GESi-0103, GESi-563, GESi-565, GESi-570, GESi-571, GESi-572
	CL-0010	5304849, 2011939PE, A041U497, A041V673, P2011939PE, A041V673 CL-1061 , VB2023 , 58831 , CL070 , X12C0-01538-VB	GESi-0067, GESi-0071, GESi-0078, GESi-0092, GESi-0106, GESi-0108, GESi-564, GESi-567, GESi-568, GESi-569
	CL-0011	A0009953933, 9953933, A0009951833 5AL003 , X12C0-01043-VB , CL077 , G03006 , CL-DD05VAM	GESi-0111
	CL-0012	279-2124, 2792124, 304-7502, 291-8515, 290-0045 CL-CAT2 , VB2031 , 46804 , CL022	GESi-0014, GESi-0042, GESi-0085
	CL-0013	278-5712, 291-8519 CL-CAT3 , VB2032 , 46805 , CL024	GESi-0038, GESi-0039
	CL-0014	224-5572, 261-2318 CL-CAT4 , VB2041	GESi-0045

****Due to industry changes, modifications and/or consolidations to aftermarket and/or OEM designs, please double-check your cross reference at www.dpfxfit.com to ensure accuracy and that you are using the most current information****

Product Image	Part Number	OEM/Aftermarket Part Numbers	GESi Units
	CL-0015	A6809950102 CL-DD02, VB2025, 35818, CL012	GESi-0028
	CL-0016	A6809950302 CL-DD03, VB2007, 35825, CL009, X1200-C0096-01	GESi-0051, GESi-0052, GESi-0081
	CL-0017	A0019959802, 998YM-1452 CL-DD04, VB2026, 35821, CL011	GESi-0027
	CL-0018	A6809950202, P238774 CL-DD15, VB2008, 35822, CL010, X12C0-01050-VB	GESi-0051, GESi-0052, GESi-0081
	CL-0019	A4709950002, 2023037/ 21048521 ,P238773 CL-DF, VB2006, 35806, CL008, X12C0-01418-VB	GESi-0011, GESi-0013, GESi-0015, GESi-0050
	CL-0020	2594128C1- 2612521C91 CL-INT, VB2015, 65834, CL016, X12C0-00948-VB	GESi-0005, GESi-0006, GESi-0008, GESi-0049, GESi-0084, GESi-525, GESi-526, GESi-541
	CL-0021	2604049C91 CL-NAV, VB2010, 35820, CL015, X12C0-01338-VB	GESi-0020, GESi-0021, GESi-519, GESi-520
	CL-0022	21212520, P238311 CL-VM2, VB2011, 82824, CL007, X12C0-01435-VB	GESi-0025, GESi-522, GESi-527, GESi-555

Product Image	Part Number	OEM/Aftermarket Part Numbers	GESi Units
	CL-0023	22778066 CL-VM3, VB2019, 82830, CL063, X12C0-C0307-01	GESi-0063
	CL-0024	22778070,21445539, 7421445539, 22936980 CL-VM4, VB2018, 8AL006, CL073, X12C0-C0307-02	GESi-0063
	CL-0025	CL-8750L	GESi-526, GESi-539, GESi-540, GESi-541
	CL-0026	CL-BOD1	GESi-0022, GESi-0035, GESi-0056, GESi-0060
	CL-0028	A0009957033, A0009956733 CL-DD08V, VB2042 , 35832, CL074, X12C0-01276-VB	GESi-0097
	CL-0029	A6809950501 CL-DD08, VB2043 , 35831, CL075	GESi-0097
	CL-0032	A0019954444, A0019954544, A0019954944, A0019955644, A0019955744, 19954444, 19954544, 19954944 5AL004, G03006, CL-DD05AM	GESi-0111


****Due to industry changes, modifications and/or consolidations to aftermarket and/or OEM designs, please double-check your cross reference at www.dpfxfit.com to ensure accuracy and that you are using the most current information****

Product Image	Part Number	OEM/ Aftermarket Part Numbers	GESi Units
	G-0001	2871451, 4965064 G-1051, G22005, 65831, GA001, X1900-C0023-01	GESi-0018, GESi-0055, GESi-0056, GESi-0060, GESi-0076, GESi-507, GESi-528, GESi-530, GESi-532, GESi-550
	G-0002	2871452, 3977531, 4965069, 2305836 G-1052, G22006, 65821, GA002, X1900-C0003-01	GESi-0009, GESi-0017, GESi-0035, GESi-0040, GESi-0044, GESi-0061, GESi-0074, GESi-501, GESi-508, GESi-509, GESi-510, GESi-515, GESi-518, GESi-528, GESi-532, GESi-533, GESi-538, GESi-543, GESi-544, GESi-556, GESi-566, GESi-601
	G-0003	2871453, 1818631PE, 21371338, 2368086, 3684079, 1818631 G-1053, G22007, 58817, GA004, X1900-C0001-01	GESi-0001, GESi-0002, GESi-0010, GESi-0012, GESi-0016, GESi-0019, GESi-0022, GESi-0023, GESi-0026, GESi-0029, GESi-0032, GESi-0033, GESi-0036, GESi-0053, GESi-0054, GESi-0057, GESi-0058, GESi-0059, GESi-0075, GESi-0077, GESi-0095, GESi-502, GESi-503, GESi-504, GESi-505, GESi-506, GESi-511, GESi-512, GESi-513, GESi-514, GESi-516, GESi-524, GESi-529, GESi-531, GESi-534, GESi-535, GESi-536, GESi-537, GESi-545, GESi-546, GESi-547, GESi-548, GESi-551, GESi-552, GESi-553, GESi-558, GESi-559
	G-0004	21371339 G-1054, G26003, 82810, GA005, X1900-C0009-02	GESi-0024, GESi-0041, GESi-521, GESi-554
	G-0005	21371340, 2866337, 1844253PE G-1055, G02003, 35814, GA040, X1900-C0016-01	GESi-511, GESi-512, GESi-513, GESi-514, GESi-516, GESi-529, GESi-535, GESi-545, GESi-546, GESi-547, GESi-548, GESi-551, GESi-553, GESi-567, GESi-568
	G-0006	2880215, A029E744, 1827320 G-1056, G02004, 58828, GA056	GESi-524, GESi-536, GESi-537, GESi-552, GESi-558, GESi-559, GESi-564, GESi-569
	G-0007	2866636, Q312526, 3846392C1, 21021846 G-1057, G02001, 35813, GA045	GESi-509, GESi-510, GESi-515, GESi-519, GESi-520, GESi-533, GESi-538, GESi-543, GESi-550, GESi-556, GESi-563

Product Image	Part Number	OEM/ Aftermarket Part Numbers	GESi Units
	G-0008	2880214, A029E743 G-1058, G02002, 58832, GA058	GESi-518, GESi-530, GESi-544, GESi-565, GESi-566, GESi-570, GESi-571, GESi-572
	G-0009	2871772, 5417860 G-1060, G02009, 58836, GA068, X1900-C0321-01	GESi-0086, GESi-0093, GESi-0094, GESi-0096, GESi-0099, GESi-0100, GESi-0101, GESi-0102, GESi-0103, GESi-563, GESi-565, GESi-570, GESi-571, GESi-572
	G-0010	5304868, 5417859, 2188190PE, 2011938PE G-1061, G02010, 58821, GA070, X1900-C0316-01	GESi-0067, GESi-0071, GESi-0078, GESi-0092, GESi-0106, GESi-0108, GESi-564, GESi-567, GESi-568, GESi-569
	G-0011	A0004911580, A0004900580, 4911580, 4900580 50902, GA077, G03006, G-DD05AM	GESi-0111
	G-0012	279-2123 G-CAT2, G01002, 46806, GA022	GESi-0014, GESi-0042, GESi-0085
	G-0013	278-5711 G-CAT3, G01003, 46807, GA024	GESi-0038, GESi-0039
	G-0014	247-1899 G-CAT4, G12004, GA006	GESi-0045

Due to industry changes, modifications and/or consolidations to aftermarket and/or OEM designs, please double-check your cross reference at www.dpffit.com to ensure accuracy and that you are using the most current information


Product Image	Part Number	OEM/ Aftermarket Part Numbers	GESi Units
	G-0015	A6804910180 G-DD02, G13005, 35816, GA012	GESi-0028
	G-0016	A6804910480 G-DD03, G03001, 35817, GA010, X1900-C0088-01	GESi-0051, GESi-0052, GESi-0081
	G-0017	A4709971145 G-DD04, G03003, 35807, GA011	GESi-0027
	G-0019	A4709970045, 21048511, 21424458 G-DD01, G03002, 35805, GA008, X1900-C0002-01	GESi-0011, GESi-0013, GESi-0015, GESi-0050
	G-0020	2594129C1, 8E7Z-5E241-B G-INT, G15001, 65832, GA016, X1900-C0020-01	GESi-0005, GESi-0006, GESi-0008, GESi-0049, GESi-0084, GESi-525, GESi-526, GESi-541
	G-0021	2604051C91 G-INTTAPE, G01101, 35823, GA015, X1900-C0079-02	GESi-0020, GESi-0021, GESi-519, GESi-520
	G-0022	21212522 G-VM3, G16001, 82825, GA007, X1900-C0064-02	GESi-0025, GESi-522, GESi-527, GESi-555
	G-0023	21570880 G-VM4, G06001, 8A1005, GA073, X1900-C0307-01	GESi-0063

Product Image	Part Number	OEM/ Aftermarket Part Numbers	GESi Units
	G-0024	23075959 G-VM5, G06002, 82829, GA063, X1900-C0307-02	GESi-0063
	G-0025	52122213AB, 2593998C1, 8E7Z-5E241-A, 15876234, 52122213AB GF-1101, G17001, 65829, GA017	GESi-0003, GESi-0004, GESi-0007, GESi-0064, GESi-0084, GESi-539, GESi-540, GESi-542
	G-0026	2593986C1, 8E7Z-5E241-C GF-1102, G17002, 65830, GA018	GESi-0003, GESi-0004, GESi-0007
	G-0027	7C3Z5H247B G-FORD, G15002	GESi-0065, GESi-0069
	G-0028	17451-E0060, 17451E0060 G-HINO2, G01302, 34801, GA030	GESi-0068, GESi-0107, GESi-0109
	G-0029	S171041930 G-ISZ, G01201, 39802, GA028	GESi-0062
	G-0030	8-97331947-0, 8973319470 G-ISZ2, G01208, GA025	GESi-0079

**** Due to industry changes, modifications and/or consolidations to aftermarket and/or OEM designs, please double-check your cross reference at www.dpfxfit.com to ensure accuracy and that you are using the most current information****

Product Image	Part Number	OEM/ Aftermarket Part Numbers	GESi Units
	G-0031	8-97611-080-0, 8-97611080-0, 8976110800, 97611808 G-ISZ3 , G01203 , 39801 , GA026	GESi-0030, GESi-0073, GESi-0098
	G-0032	8-97628257-0, 8976282570 G-ISZ5 , G01202 , 58841 , GA027	GESi-0073, GESi-0079, GESi-0098, GESi-0110
	G-0033	21095726, 3853371C1, Q312516 G-VM2 , G16003 , 82820 , GA042	GESi-522, GESi-527, GESi-555
	G-0034	A0004921680 G-DD08 , G03007 , 35833 , GA074	GESi-0097
	G-0039	S17451-78070 G01304	GESi-0110

** Due to industry changes, modifications and/or consolidations to aftermarket and/or OEM designs, please double-check your cross reference at www.dpfxfit.com to ensure accuracy and that you are using the most current information**



Even a minor leak between flanges can cause catastrophic failure in your emission control system. All of our gaskets are made to OEM standards, utilizing the highest quality materials and innovative construction. DPFxFIT™ gaskets include an integrated wire mesh within the graphite to ensure the highest level of strength and support, to maintain integrity and quality of seal.

Delivery Lead Times

Standard:

- ✕ **GESi® Toronto** 2:00PM EST order cut off
- ✕ **GESi® Charlotte** 3:00PM EST order cut off
- ✕ **GESi® Edmonton** 4:00PM EST order cut off
- ✕ **GESi® Vancouver** 5:00PM EST order cut off
- ✕ Orders received prior to the cut off times will ship same day on a prepaid 2-day service level. Based on the customer’s proximity from the DPFxFIT™ shipping location, order(s) could arrive next day.

Expedited:

Next Day Air Service Level Flat Rate:

Canada Wide	\$200.00 CAD
Continental USA	\$150.00 USD



Genuine OE Sensor Program Available to the Aftermarket!

DPFXFIT™ has sourced a line of sensors built in the USA to ensure exact fit, function, and superior performance. Engineered and manufactured by the Tier 1 OE supplier, each sensor is produced with the same high-quality materials used by leading truck manufacturers and follow all Continental protocol with authentic ceramic NGK probes. Just like our aftertreatment products, you benefit from components that are never remanufactured, ensuring no core charge, which reduces costs and maximizes profitability.

Unlike remanufactured alternatives, our NOx sensors are 100% Genuine OE, making them the preferred choice for professional technicians nationwide. With coverage for Medium Duty, and Vocational, as well as Class 7 & 8 Heavy Duty trucks, DPFXFIT™ ensures quality, application coverage, and full support. Available for all leading engine and truck brands like Cummins, Mack, Volvo, & Detroit.

Lifespan and Failure:

NOx sensors have a lifespan, typically between 100,000 to 150,000 miles. The longevity of these sensors is influenced by engine operating conditions. When a NOx sensor fails, faults are logged by the engine control module and displayed on the dashboard. In such cases, the engine may default to emergency mode, resulting in increased fuel consumption and slight stalls.

Causes of Failure:

- Soot buildup
- Excessive water in the exhaust stream
- Unburned fuel or carbon

Symptoms of Failing NOx Sensors:

- Increase fuel consumption
- Unstable idle

DPFXFIT™ NOx Sensors

Product Image	Part Number	Application	OEM/Aftermarket Part Numbers
	SENN-0003XF	CUMMINS	4326475, 4326867, 5305727, A044C666, A045S161, 5WK9 6754C, 5WK96754C NOX-CXX-020, 5EL010
	SENN-0005XF	CUMMINS	1924000, 1954664PE, 1954664PRX, 2520640C1, 2872942, 2872942NX, 4326872, 4326872RX, 5WK96749B, A034M369, A045S169, 5WK9 6749B NOX-CNP-017, 5EL006, SNX005, ANX005
	SENN-0009XF	DETROIT DIESEL	08202764, 101532328, 8202163, A0091530728, A0101532328, EA0101532328, 5WK9 7339A, 5WK97339A NOX-DXX-005, 51037, 3FL002, SNX101, ANX101
	SENN-0010XF	DETROIT DIESEL	5WK97338A, 8202163, A0091530628, A0101532228, 5WK9 7338A NOX-DXX-012, 3FL001, SNX103, ANX103
	SENN-0011XF	CUMMINS	4326470, 4326862, A044C659, A045S156, 5WK9 6751A, 5WK96751A NOX-CPX-026, 22038, SNX014
	SENN-0012XF	CUMMINS	4326476, 4326868, A044C669, A045S162, 5WK9 6752C, 5WK96752C 22035, ANX013
	SENN-0013XF	CUMMINS	2897307, 4326472, 4326864, A034X869, A044C661, A045S158, 5WK9 6750C, 5WK 6750C 22028, ANX008

Due to industry changes, modifications and/or consolidations to aftermarket and/or OEM designs, please double-check your cross reference at www.dpfxfit.com to ensure accuracy and that you are using the most current information

Product Image	Part Number	Application	OEM/Aftermarket Part Numbers
	SENN-0018XF	DETROIT DIESEL	82394137, A0101538128, 5WK9 7403, 5WK97403 NOX-DXX-027, 3FL009, SNX102, ANX102
	SENN-0022XF	CUMMINS	2872944, 3687930, 4326870, A034M373, A045S167, 5WK9 6740B, 5WK96740B NOX-CXX-007, 5EL012, SNX001, ANX001
	SENN-0023XF	CUMMINS	2872946, 4326874, A034M375, A045S171, 5WK9 6741B, 5WK96741B NOX-CXX-003, 5EL005, SNX002, ANX002
	SENN-0024XF	CUMMINS	2872948, 4326873, 5295473, A034M378, A045S170, 5WK9 6742B, 5WK96742B NOX-CNX-016, 5EL004, SNX004, ANX004
	SENN-0025XF	VOLVO	22303390, 5WK97367, 22303391, 5WK9 7367 NOX-VXX-002, NOX-VXX-001, 8CL001, 8CL002, SNX601, SNX602, ANX601, ANX602
	SENN-0026XF	CUMMINS	4327153, A047R390, 5WK9 6760A, 5WK96760A 5EL146
	SENN-0028XF	VOLVO	22303391, 5WK97366, 5WK9 7366 NOX-VXX-001, 8CL002, SNX602, ANX602
	SENN-0029XF	VOLVO	22303384, 5WK97365, 5WK9 7365 NOX-VXX-008, 8CL003, SNX603, ANX603

Product Image	Part Number	Application	OEM/Aftermarket Part Numbers
	SENN-0030XF	DETROIT DIESEL	A0101531928, 5WK97341A, 5WK9 7341A NOX-DXX-009, 3FL008, SNX104
	SENN-0032XF	CUMMINS	1906307, 1954665PRX, 1954666PE, 1954666PRX, 2872947, 2872947NX, 4326869, 4326869RX, 5WK96753B, A034M377, A045S164, 5WK9 6753A NOX-CXX-011, 5EL013, SNX003, ANX003
	SENN-0034XF	PACCAR	2006246, 2006246, 2205166, 2236409 NOX-PXX-010, 5EL008, 5EL036, 22025, SNX501, ANX501
	SENN-0043XF	DETROIT DIESEL	82383556, A0111531728 3FL049, SNX108
	SENN-0044XF	NAVISTAR / INTERNATIONAL	7503569C1 SNX403
	SENN-0045XF	NAVISTAR / INTERNATIONAL	7502711C1 SNX402
	SENN-0046XF	RAM	68447681AA

****Due to industry changes, modifications and/or consolidations to aftermarket and/or OEM designs, please double-check your cross reference at www.dpfxfit.com to ensure accuracy and that you are using the most current information****

Product Image	Part Number	Application	OEM/Aftermarket Part Numbers
	SENN-0048XF	RAM	68210084AA
	SENN-0049XF	FORD	HC3A5L248CA, HC3A5L248CB, HC3Z5L248A
	SENN-0050XF	NAVISTAR / INTERNATIONAL	7099784C1 NOX-CNX-016, 5EL004, SNX401
	SENN-0051XF	GENERAL MOTORS	12695882, 12708006, 7505103C1
	SENN-0052XF	GENERAL MOTORS	12695881, 12708005
	SENN-0053XF	RAM	68460215AA, 68460215AB, AAA20950100
	SENN-0054XF	FORD	LC4A5L248AA, LC4A5L248AB, LC4A5L248AC, LC4Z5L248A, LC4Z5L248B
	SENN-0055XF	FORD	LC3A5L248AA, LC3A5L248AB, LC3A5L248AC, LC3Z5L248A

Product Image	Part Number	Application	OEM/Aftermarket Part Numbers
	SENN-0056XF	GENERAL MOTORS	12643694, 12673517, 12676706, 12680469, 12718676
	SENN-0057XF	GENERAL MOTORS	12643693, 12673516, 12676705, 12680215, 12680619, 12718675, 12718742
	SENN-0058XF	RAM	68460218AA, 68460218AB, AAA20950600
	SENN-0059XF	GENERAL MOTORS	12680288, 12694400, 12696465, 24001900
	SENN-0060XF	RAM	68366500AB, 68366500AC
	SENN-0061XF	RAM	68307226AA, 68307226AB, 68307226AC
	SENN-0062XF	RAM	68375474AC

****Due to industry changes, modifications and/or consolidations to aftermarket and/or OEM designs, please double-check your cross reference at www.dpfxfit.com to ensure accuracy and that you are using the most current information****

Follow us online at:



GESi® founder and CEO, Eric Latino is a distinguished Canadian entrepreneur and accomplished drag racer, renowned for his leadership of Global Emissions Systems Inc. (GESi®) and his significant contributions to the drag racing community. Eric's journey from a young automotive enthusiast to a leading figure in the drag racing community is a testament to his unwavering commitment to innovation, performance, and family, with his legacy now extending to the next generation, as his son Matthew begins his own promising racing career alongside him.

Eric's unique blend of business insight and racing experience has paved the way for groundbreaking partnerships. By incorporating GESi's® catalytic converters into his Pro Stock racing efforts, he strives to boost engine performance without compromising environmental regulations. This move showcases his dedication to balancing high performance with sustainability.

Eric, driver of the GESi® Chevrolet Camaro is a NHRA national record holder in 2017 in Pro Mod and 2019 Canadian Drag Racing Hall of Famer with a career best ET of 6.501. He made his Pro Stock debut in June 2023 during the Summit Racing Equipment NHRA Nationals making him the first Canadian driver to compete in the class since the mid 2010's.

Now a co-owner of the KB Titan brand, Eric has managed to marry his business into drag racing. KB Titan Racing is one of the premier Pro Stock teams in the NHRA (National Hot Rod Association), known for its dedication, innovation, and relentless pursuit of excellence on the track. With a legacy of championship wins and a lineup of talented drivers, KB Titan Racing consistently pushes the limits of performance in the highly competitive Pro Stock class. Backed by a team of skilled engineers, crew members, and passionate supporters, the team continues to set new standards in speed and precision.



Contact us today

orders@gesi.us

1-888-758-4374

GLOBAL EMISSIONS SYSTEMS INC.

1680 McEwen Drive, Whitby
Ontario, L1N0A2

GLOBAL EMISSIONS SYSTEMS INC. USA

158 Houston Road, Troutman
North Carolina, 28166